



## IMMEDIATE SUSPENSION OF THE USE OF FAMECA FC 5300 LV CABLE IDENTIFIER

### OVERVIEW

Following an incident where this identifier incorrectly identified other cables.

The **IMMEDIATE SUSPENSION** of the use of Fameca FC 5300 LV cable identifier is now in force.



### WHAT YOU NEED TO DO

- All Fameca FC 5300 LV cable identifiers are to be returned to line managers for quarantine.
- Other means of identifying cables are available; please follow DSR 01 018.

### DETAIL

Following the identification of potential issues with the Fameca FC 5300 LV it has been decided that these shall be quarantined immediately until further notice.

Other means of identifying cables are available; please follow DSR 01 018.

---

It is the responsibility of line management to ensure all appropriate employees are issued with this document and to check their understanding of its content. This document will be subject to compliance audits within 14 days from the date of issue.

---